



HOUSTON FIRE DEPARTMENT NEWS RELEASE

PUBLIC INFORMATION OFFICE

DATE: 12.13.2005

INCIDENT UPDATE – 10601 SABO RD.

Houston firefighters were dispatched to an apartment fire at 10601 Sabo Rd. in Southeast Houston, Monday, Dec. 12, 2005 at 4:30 p.m. and arrived on scene with fire coming from the 2nd floor apartments and roof area of one building.

The two-alarm fire was tapped out at 5:15 p.m. Four units were totally damaged, four suffered major water and smoke damage and two additional units received minor damage. There were no reported injuries.

The cause of the fire was ruled as accidental due to an unspecified electrical short in the attic area.